

<p align="center">RFP #13-14-102 PROFESSIONAL SERVICES FOR INSPECTION OF ELECTRICALLY OPERATED PARTITIONS, ROLL DOWN CURTAINS AND BLEACHERS OPEN: 4/29/14 - AT: 2:30 P.M.</p>	<p>Nickerson Corp.</p>		<p>S.L. Installation</p>							
<p>FEE \$ _____</p>	<p align="right">\$64,680</p>		<p align="right">\$19,500</p>							
<p>Following inspections, any minor repairs necessary to correct deficiencies which include but are not limited to key switch or cage replacements, sensor replacements or adjustments, control box relays (up to a maximum of \$750 per school) must be pre-approved by BPS Director of Safety and Health before any materials are purchased or work is started</p> <p>Estimated amount for repairs</p> <p align="right">Total</p>	<p align="right">\$10,000</p> <p align="right">\$74,680</p>		<p align="right">\$10,000</p> <p align="right">\$29,500</p>							
<p>BUFFALO BOARD OF EDUCATION SUMMARY: S.L. Installation \$29,500</p>	<p>\$530/bleacher \$470/operable wall \$470/dividing curtain</p>									